Approved For Release 2003/03/28 : CIA-RDP78T05161A001300010003-2 25X1 MAGERY NALYSIS IVISION PHOTOGRAPHIC INTELLIGENCE REPORT STATUS OF NORTH VIETNAMESE RAILROADS

DECLASS REVIEW by NIMA/DOD

REPORT NO. 24 CIA/PIR 75080

**DATE JAN. 1967** 

GROUP 1 Excluded from automatic downgrading and declassification

SECRET

Approved For Release 2003/03/28 : CIA-RDP78T05161A001300010003-2

#### Approved For Release 2003/03/28: CIA-RDP78T05161A001300010003-2

#### WARNING

This document contains information affecting the national defense of the United States, within the meaning of Title 18, sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law.

Approved For Release 2003/03/28	СА-RDP78T05161A001300010003-2
ZECH	(E

PIR 75080

25X1

CIA IMAGERY ANALYSIS DIVISION

PREFACE


This report summarizes signficant items of photo intelligence relating to the North Vietnamese railroad system which has been developed from available photography (received by the CIA Imagery Analysis Division) during the period indicated on the cover. This report is intended to provide a comprehensive view of the railroad system and does not necessarily reflect the most recent status changes as reported by pilots' reports or field photo intelligence cables.

The railroad system has been broken down into 5 major lines: the Hanoi/Lao Cai Line, the Hanoi/Dong Dang Line, the Hanoi/ Haiphong Line, the Hanoi/Dong Hoi Line and the Thai Nguyen Line (Figure I). Annotated maps and photos are used to show the status of each line.

-1-



PIR 7508025X1 FIGURE 1



**SECRET** 

Approved For Release 20(3/03/28 : CIA-RD)P78T05161A001300010003-2

Approved For Release	2003/03/28 - CIA-RDP78T05161A001300010	003-2
	NEL RE I	

<b>* - - -</b> · · · · · · · · · · · · · · · · · · ·	
CIA IMAGERY ANALYSIS DIVISION	PIR 75080

### SUMMARY


Those portions of the Hanoi/Lao Cai and Hanoi/Dong Dang Rail Lines covered by interpretable photography were open to through traffic. Four bridge interdictions were noted on the Hanoi/Dong Hoi Rail Line. Work continues on the railroad by-pass route around Hanoi.

## CONTENTS

Hanoi/Lao Cai Rail Line	Page	4
Hanoi/Dong Dang Rail Line		6
Hanoi/Dong Hoi Rail Line		8
Hanoi/Haiphong Rail Line		15
Thai Nguyen Rail Line		16

-3-

25X1



# Approved For Release 2003/03/28 REHA-RDP78T05161A001300010003-2

PIR 75080

CIA IMAGERY ANALYSIS DIVISION

ITEM OF INTEREST NO. 1: Hanoi/Lao Cai Rail Line

NAME

: Lenh Khanh RR. Bridge SE

BE

25X1

:

COORDINATES

: 21 34N - 104 59E, VJ 991859

PHOTO REFERENCE


•


25X1

MAP REFERENCE

: JOG (A) 1501, NF 48-10

The Lenh Khanh Railroad Bridge has been repaired and is now serviceable to through rail traffic. One abutment of the original single-span, half-through truss bridge is completely destroyed. This void has been spanned by a 20' (approx.) deck section.





## Approved For Release 2003/03/28 RETA-RDP78T05161A001300010003-2

CIA IMAGERY ANALYSIS DIVISION	PIR 75080

. .

25X1

25X1

ITEM OF INTEREST NO. 1: Hanoi/Dong Dang Rail Line

NAME : Yen Vien Railroad Classification Yard


BE :

COORDINATES : 21 05N - 105 55E, WJ 955314

PHOTO REFERENCE :

MAP REFERENCE : JOG (A) 1501, NF 48-11

The Yen Vien Railroad Classification Yard has been damaged by bombing. The choke point at the northern end of the yard has been partially interdicted and is now undergoing repair. Four tracks remain unserviceable. The bulk of the yard is undamaged.



-7-

Approved For Release 2003/03/28 : CIA-RDP78 05161A001300010003-2

# Approved For Release 2003/03/28 : CIA-RDP78T05161A001300010003-2

### **SECRET**

CIA IMAGERY ANALYSIS DIVISION

PIR 75080

**-**25X1

25X1

ITEM OF INTEREST NO. 1: Hanoi/Dong Hoi Rail Line

NAME

: Yen Hoi Ha RR. Bridge

BE

25X1

:

COORDINATES

: 18 15N - 105 40E, WF 717189


PHOTO REFERENCE

\_\_\_\_\_

MAP REFERENCE

: JOG (A) 1501, NE 48-7

One span of the 3 span, deck-type Yen Hoi Ha Railroad Bridge has been dropped, and the other two spans have sustained heavy damage. Both approaches have been interdicted and the rail has been removed from the bridge and adjacent roadbed.



-9-

**SECRET** 

25X1

### Approved For Release 2003/03/28 PGHA-RDP78T05161A001300010003-2

25X1

CIA IMAGERY ANALYSIS DIVISION

PIR 75080

ITEM OF INTEREST NO. 2: Hanoi/Dong Hoi Rail Line

NAME

: Dia Thuy RR. By-pass Bridge NW

ΒE

25X1

COORDINATES

: 19 23N - 105 43E, WG 756417

PHOTO REFERENCE

•


MAP REFERENCE : JOG (A) 1501, NE 48-3

The Dia Thuy Railroad By-pass Bridge NW has been repaired and is now serviceable. A second by-pass bridge is under construction approximately 700' north of the main bridge which remains unserviceable.

25X

25X1

25X1



Approved For Rei	eas	SECRET	25X1
		CIA IMAGERY ANALYSIS DIVISION	PIR 75080
ITEM OF INTEREST NO. 3	}:	Hanoi/Dong Hoi Rail Line	
NAME	:	Loop siding under construction	ı .
BE	:	NA	
COORDINATES	:	19 27N - 105 46E, WG 808520	
PHOTO REFERENCE	:[		25X1
MAP REFERENCE	:	AMS 1701. Sheet 6169 II	

A 0.7 nm (approx.) loop siding is under construction from UTM WG 808522 to UTM WG 807517. Due to its configuration, it can be used as a passing track or as a storage siding. Approximately 14 small flat cars are located on an existing siding 0.1 nm S of the southernmost junction of the new spur with the main line.



Approved For R	kelease 2003/0 <b>3/ᢓ€R</b> Ē <b>I</b> A-RDP78T05161	A001300010003-2
25X1		•
'	CIA IMAGERY ANALYSIS DIVISION	PIR 75080

ITEM OF INTEREST NO. 4: Hanoi/Dong Hoi Rail Line

NAME

: Construction

ΒE

: NA

COORDINATES

: 20 59N - 105 54E

PHOTO REFERENCE

:|

MAP REFERENCE

: JOG (A) 1501, NF 48-15

Work continues on the northern section of the railroad by-pass route around Hanoi (see Report No. 19). Probable tracks has been laid from its junction with the Hanoi/Haiphong Rail Line at UTM WJ 988236 to UTM WJ 959207, a distance of approximately 2.5 nm. Probable ballast has been laid beyond the railhead and on at least 1 ferry approach.

25X1

On the southern section of the by-pass, ballast has been laid northward to UTM WJ 929193.


No work has been undertaken on the actual ferry slips on the Red River.

# Approved For Release 2003/03/36 C REP-RDP78T05161A001300010003-2

25X1

CIA IMAGERY ANALYSIS DIVISION

PIR 75080



-14-

#### Approved For Release 2003/03/28: CIA-RDP78T05161A001300010003-2

**SECRET** 25X1 PIR 75080 FIGURE 11 HANO 12100N 10600E KEY All Maps within this report have been keyed in the following manner: \* Main bridge bombed - now serviceable.  $\bigstar$  By-pass bridge or bridges serviceable. ☐ Main bridge unserviceable. All bridge crossing facilities unserviceable. ▲ By-pass bridge under construction. \_\_Original bridge has not been damaged or destroyed based on available photography. Extent of rail line covered by available, interpretable photography. Item of interest. Turn to the item number within the section for further information. HAI DUONG 2100N 10630E HANOI - HAIPHONG RAILROAD Railroad Streams ~~~ Bridge No. & location 3 statute miles 10 HAIPHONG -15-

SECRET

#### Approved For Release 2003/03/28 : CIA-RDP78T05161A001300010003-2

SECRET


PIR 75080 FIGURE 12 25X1

KEY

All Maps within this report have been keyed in the following manner:

- ☆ Main bridge bombed now serviceable.
- \* By-pass bridge or bridges serviceable.
- Main bridge unserviceable.
- All bridge crossing facilities unserviceable.
- ▲ By-pass bridge under construction.
- .\_\_Original bridge has not been damaged or destroyed based on available photography.
- Extent of rail line covered by available, interpretable photography.
- Item of interest. Turn to the item number within the section for further information.

All intelligence developed within the reporting period is printed in red; older intelligence is printed in black.



-16-

ved For Release 200			
		,	
·			
	÷		
·			